

# CERTIFICATE OF COMPLIANCE

CERTIFICATE NUMBER: 180899 - E202878

Page 1 of 1

ISSUE DATE: August 18, 1999

Issued to: Erico Inc.  
34600 Solon Road  
Solon, OH 44139

Report Reference: E202878, June 17, 1999


This is to Certify that  
representative samples of: Type E1 Copper Stranded Lightning Conductors  
Dynamics Air Terminal

Have been investigated by Underwriters Laboratories Inc.® in accordance with the Standard(s)  
indicated on this Certificate.


Standard(s) for Safety: UL 96 - Lightning Protection Components


Additional Information: None

Only those products bearing the UL Listing Mark should be considered as being covered by  
UL's Listing and Follow-Up Service.

The UL Listing Mark generally includes the following elements: the symbol UL in a circle:  with the word "LISTED"; a control  
number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL  
Directory.

**LOOK FOR THE UL LISTING MARK ON THE PRODUCT**

Engineer:   
Jake Killinger/Staff Engineer  
Underwriters Laboratories Inc.

Review Engineer:   
R. Hames/Assoc. Mng. Engr.  
Underwriters Laboratories Inc.